

# BUNTING BEARINGS, LLC

200 Van Buren Street \* Delta, Ohio 43515 \* (419) 822-3483 \* Fax: (419) 822-3372

## Material Safety Data Sheet

### Bunting Continuous Cast

Revised: June 1, 2009

#### Section I – Material Identification

**Manufacturer:** Bunting Bearings, LLC  
200 Van Buren Street  
Delta, Ohio 43515

**Emergency Telephone Number**  
419-866-7000

**Information Telephone Number**  
419-522-3323

**Product Class:** Cast Bronze Alloys  
C83600 through C94300  
Bunting M-37 through M-66

#### Section II – Hazardous Ingredients / Identity Information

| Hazardous Ingredient(s) | CAS Number | OSHA PEL               | ACGIH TLV              | Percent Range |
|-------------------------|------------|------------------------|------------------------|---------------|
| <b>Base Metal:</b>      |            |                        |                        |               |
| <b>Copper</b>           | 7440-50-8  | 1.0 mg/m <sup>3</sup>  | 1.0 mg/m <sup>3</sup>  | dust 65-90%   |
| <b>Copper</b>           | 7440-50-8  | 0.1 mg/m <sup>3</sup>  | 0.2 mg/m <sup>3</sup>  | fume          |
| <b>Alloys:</b>          |            |                        |                        |               |
| <b>Lead</b>             | 7439-92-1  | 0.05 mg/m <sup>3</sup> | 0.15 mg/m <sup>3</sup> | 0.2-24.5%     |
| <b>Tin</b>              | 7440-31-5  | 2.0 mg/m <sup>3</sup>  | 2.0 mg/m <sup>3</sup>  | 2-16%         |
| <b>Zinc</b>             | 7440-66-6  | 15.0 mg/m <sup>3</sup> | 10.0 mg/m <sup>3</sup> | dust 0.25-10% |
| <b>Zinc</b>             | 7440-66-6  | 5.0 mg/m <sup>3</sup>  | 5.0 mg/m <sup>3</sup>  | fume          |
| <b>Nickel</b>           | 7440-02-0  | 1.0 mg/m <sup>3</sup>  | 1.0 mg.m <sup>3</sup>  | 0.5-5.25%     |

**HMIS Rating:** Lead/Copper, Health 2, Flammability 0, Reactivity 0

#### Section III – Physical/Chemical Characteristics

**Boiling Point:** N/A      **Specific Gravity (H<sub>2</sub>O = 1):** 7.5-9.0

**Vapor Pressure:** N/A      **Melting Point:** 1500F – 1950F

**Vapor Density:** 0.27-0.323 1      **Evaporation Rate:** N/A

**Solubility in Water:** Insoluble

**Appearance:** Yellow to Red

**Odor:** None

#### Section IV – Fire and Explosion Data

**Flash Point:** N/A      **Flammable Limits: Upper:** N/A

**Method:** N/A      **Lower:** N/A

**Extinguishing Media:** Solid form – None  
Fine Chips/Dust – Use a dry chemical or sand

**Special Fire Fighting Procedures:** Protective Clothing  
NIOSH-self contained breathing apparatus

**Unusual Fire and** Fine chips or dust may ignite and should be stored  
**in**

**Explosion Hazards:** a well ventilated area.

---

## Section V – Reactivity Data

---

|                             |                                                                                                                                                                  |
|-----------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>Stability:</b>           | Copper alloys are stable under normal conditions of use storage and transportation.                                                                              |
| <b>Conditions to Avoid:</b> | Molten metal may react violently with water.<br>Avoid contact of chips and dust with heat, oxidizers, acids, alkali's, molten lithium and halogenated compounds. |
| <b>Incompatibility:</b>     | Avoid acids, bases and oxidizers.                                                                                                                                |

**Hazardous Polymerization:** Will not occur.

---

## Section VI – Health Hazard Data

---

**Routes of Entry:** Inhalation, Eye, Skin and Ingestion.

### Health Hazards:

**Copper:** Under normal handling and use, exposure to the solid form of copper alloys presents few health hazards. Thermal cutting, melting, machining or grinding may produce fumes or dust containing the component elements and breathing these fumes or dust may present potentially significant health hazards. The exposure levels in Section II are relevant to fumes and dust. Fumes of copper and manganese may cause metal fume fever with flu-like symptoms, and copper may cause hair discoloration. Copper fumes and dust irritate the nose and throat. If too many fumes are inhaled, it will cause a sweet or metallic taste in the mouth. Inhaling excessive amounts of copper dust and fume over a long period of time can cause anemia.

**Lead – Short Term Exposure:** Lead is an accumulative poison. Inhalation effects of exposure to fumes or dust of inorganic lead may not develop quickly. Symptoms may include decreased physical fitness, fatigue, sleep disturbance, headache, aching bones and muscles, constipation, abdominal pains and decreasing appetite. The effects are reversible and complete recovery is possible. Inhalation of large amounts of lead may lead to seizures, coma and death.

**Lead – Long Term Exposure:** Long-term exposure to lower levels can result in a buildup of lead in the body and more severe symptoms. Prolonged exposure may also result in kidney damage. Continuous exposure can result in decreased fertility, and exposure of the mother during pregnancy can cause birth defects.

**Iron Oxide and Tin:** Chronic overexposure to iron oxide or tin fumes may cause an apparent benign pneumoconiosis. In the case of iron oxide, this is called siderosis, and for tin it is called stannosis.

**Zinc Oxide:** Overexposure to zinc oxide fumes can cause “Metal Fume Fever”.

**Nickel:** Under normal handling, exposure to nickel presents few health hazards. Dust may cause headache, coughing, dizziness or difficult breathing. Prolonged exposure may cause dermatitis. Ingestion may cause nausea, vomiting, headaches, dizziness, and gastrointestinal irritation.

**Carcinogen:** None for the alloys.  
Nickel is considered a possible carcinogen by NTP and IARC.

**Emergency and First Aid Procedures:**

- Ingestion:** If swallowed and the person is conscious, immediately give large amounts of water. Get medical attention.
- Inhalation:** If a person breathes in large amounts of dust or fume, move the exposed people to fresh air. Get medical attention.
- Eye Contact:** Immediately flush with plenty of water for at least 15 minutes. Get medical attention.
- Skin Contact:** Immediately wash with plenty of soap and water.

---

**Section VII – Precautions for Safe Handling and Use**

---

**Steps to be taken in case material is released or spilled:**

No special precautions are necessary for spills of bulk materials. If large quantities of dust are spilled, remove by vacuuming or wet sweeping to prevent heavy concentrations of airborne dust. Respirators and protective clothing are recommended.

**Waste Disposal Method:**

Follow Federal, State and local regulations regarding disposal. Scrap metals can generally be reclaimed and recycled.

**Precautions to be taken in handling and storing:**

Use good safety practices. Store dust away from sources of ignition.  
Keep dust dry and away from exposure to water.

---

**Section VIII – Control Measures**

---

- Respiratory Protection:** When required, employees should wear MSHA or NIOSH approved respirators for protection against airborne dust or fumes.
- Ventilation:** Use general or local exhaust ventilation to keep airborne concentrations of dust and fumes below the TLV.
- Protective Gloves:** N/A
- Eye Protection:** Approved safety glasses and/or goggles should be worn during any machining, grinding, cutting, or other operation from which airborne particles may be emitted.
- Other Protective Clothing:** N/A
- Work/Hygienic Practices:** Wash hands after handling materials.  
Food or drink should not be consumed in the work area.  
Wash hands and face prior to eating, drinking or smoking.

---

### **Section 313 – Supplier Notification**

---

These products contain copper, lead, zinc, tin and nickel which are all subject to the annual reporting requirements of Section 313 of the Emergency Planning and Community Right to Know Act of 1986 and of 40 CFR 372.

The above information is furnished without warranty, expressed or implied, except that it is accurate to the best knowledge of Bunting Bearings LLC. The data on these sheets relates only to the specific material designated herein. Bunting Bearings LLC assumes no legal responsibility for use or reliance upon this data.